

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

FK831 I/A/O AVENUE W & EAST 5TH ST  
NE AVENUE W & EAST 5TH ST  
> 1 BROOKLYN, NY

NY Spills S110242524  
N/A

1.134 mi.  
5985 ft.

Site 2 of 2 in cluster FK

Relative:  
Higher

SPILLS:

Actual:  
12 ft.

Name: I/A/O AVENUE W & EAST 5TH ST  
Address: AVENUE W & EAST 5TH ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0912241 / 2010-02-26  
Facility ID: 0912241  
Facility Type: ER  
DER Facility ID: 374029  
Site ID: 425118  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2010-02-23  
Investigator: smsanges  
Referred To: Not reported  
Reported to Dept: 2010-02-23  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial Vehicle  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: Not reported  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2010-02-23  
Spill Record Last Update: 2010-02-26  
Spiller Name: MELISSA WHITLEY  
Spiller Company: NYC DEP  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: MELISSA WHITLEY  
DEC Memo: "minor spill - cleanup completed"  
Remarks: "1 gallon of hydraulic fluid to a catch basin clean up in progress."

All Materials:

Site ID: 425118  
Operable Unit ID: 1180849  
Operable Unit: 01  
Material ID: 2174852  
Material Code: 0010  
Material Name: hydraulic oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 1.00  
Units: G  
Recovered: 1.00  
Oxygenate: Not reported